

City of Brockton

Procurement Department

MICHAEL C. MORRIS, MBA CHIEF PROCUREMENT OFFICER

ADDENDUM #1

To:

All Interested Parties

From: Michael Morris, Chief Procurement Officer

Subj: Addendum #1 to BD-RFQ23-TILE (ASBESTOS TILE REMEDIATION)

Date: January 26, 2023

Total Pages: 1

Responses to Questions & Clarifications

- 1. Are the floors wood or concrete? They are wood.
- 2. Is the mastic/glue hot as well or just the tiles, it says nothing about the glue? Assume the mastic is ACM. The quote should include removing the mastic-covered substrate.
- 3. It states remediation of 2 floors but both items are on the second-floor main room & hallway and second-floor office. Is the abatement on 1 floor? The terminology of "2 floors" indicates that two separate areas, or floors, are to be removed. They both occur on the second level.
- 4. Is the intent to remove only the floor tile or will we be required to remove the layer of mastic-coated plywood as well as the floor tile?

The quote should include removing the mastic-covered substrate.

5. Will the rooms be emptied or will we be required to move the furnishings from the rooms? (pool table etc.) The rooms will be clear of all furniture and moveable objects.

"City of Champions"